Service Update

17107 Rear Back Glass Water Leak



Reference Number: N162078080 Release Date: March 2017

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the

dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited

Warranty period.

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Colorado	2017	2017		
GMC	Canyon	2017	2017		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2017 model year Chevrolet Colorado and GMC Canyon vehicles with a sliding rear window			
	may have a small hole in the casing surrounding the glass. Customers may experience water intrusion into the rear passenger compartment, and the seats or trim may get wet.			
Correction	Dealers are to apply seam sealer to cover the small hole in the casing.			

Parts

Quantity	Part Name	Part No.
1 (Submit	Quick Seal 2000 Black Seam Sealer	KT12592*
as a Net		
Item)		

^{*} Contact Kent Automotive at 1-888-937-5368 (USA), 1-800-563-1717 (Canada), or www.kent-automotive.com. Dealers that do not have a Kent Automotive account or representative must advise the Customer Service Representative that the sealer is being used for this GM bulletin to obtain special bulletin pricing. **Do not order from GMCCA.**

Warranty Information

Labour		Labour	Trans.	
Operation	Description	Time	Type	Net/Miscellaneous
9103094	Apply Seam Sealer	0.3	ZFAT	*

^{*} Sealer needed to perform the required repairs, not to exceed \$22.00 USD, \$17.20 CAD. This allowance includes reimbursement for the sealer, handling, and any shipping incurred.

Service Procedure



4756485

Service Update

17107 Rear Back Glass Water Leak





4756486

- 1. Approximately 25 mm (1 in) inboard from the roof panel joint finish moulding, with a trim tool, carefully pull back the rear sliding window moulding as shown. Both sides (driver and passenger) should be sealed.
- 2. Clean the area to remove any debris or water.



4756488

3. Apply a small bead of Quick Seal 2000 Black Seam Sealer to cover the small hole in the casing.



4756491

4. Push the rear sliding window moulding back in place.

Service Update

17107 Rear Back Glass Water Leak



Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.